



2005
January 18, 2004

Mr. Roger Westman
Allegheny County Health Department
Department of Air Quality
301 Thirty-ninth Street
Pittsburgh, PA 15201

Dear Mr. Westman:

Subject: 40 CFR §63.311(d)
NESHAP Semi-annual Compliance Certification

Please accept this submittal as the Semi-annual Compliance Certification for United States Steel, Clairton Coke Works for the period of July 1, 2004 through December 31, 2004 according to the reporting requirements of 40 CFR §63.311(d).


During the periods stated above no coke oven gas was vented except through the bypass/bleeder stack flare system of Batteries 1, 2, 3, 7, 8, 9, 13, 14, 15, 19, 20, or B.

During the periods stated above there were no startup, shutdown, or malfunction events for Batteries 1, 2, 3, 7, 8, 9, 13, 14, 15, 19, 20, or B that required the implementation of §63.310.

During the periods stated above work practices were not implemented under §63.306 at Batteries 1, 2, 3, 7, 8, 9, 13, 14, 15, 19, 20, or B.

If you have any questions regarding this submittal, please direct them to Coleen Davis at 412-233-1015 or cdavis@uss.com.

Sincerely,


Michael E. Hohman
Manager, Environmental

cc: Judith Katz, EPA III

APR 12 2004
AIR PROTECTION DIVISION (3AP12)

JAN 24 2004

RECEIVED



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

July 13, 2004

Mr. Roger Westman
Allegheny County Health Department
Department of Air Quality
301 Thirty-ninth Street
Pittsburgh, PA 15201

Dear Mr. Westman:

Subject: 40 CFR §63.311(d)
NESHAP Semi-annual Compliance Certification

Please accept this submittal as the Semi-annual Compliance Certification for United States Steel, Clairton Coke Works for the period of January 1 through June 30, 2004 according to the reporting requirements of 40 CFR §63.311(d).

During the periods stated above no coke oven gas was vented except through the bypass/bleeder stack flare system of Batteries 1, 2, 3, 7, 8, 9, 13, 14, 15, 19, 20, or B.

During the periods stated above there were no startup, shutdown, or malfunction events for Batteries 1, 2, 3, 7, 8, 9, 13, 14, 15, 19, 20, or B that required the implementation of §63.310.

During the periods stated above work practices were not implemented under §63.306 at Batteries 1, 2, 3, 7, 8, 9, 13, 14, 15, 19, 20, or B.

If you have any questions regarding this submittal, please direct them to Coleen Davis at 412-233-1015 or cdavis@uss.com.

Sincerely,

A handwritten signature in cursive script that reads "Michael E. Hohman".
Michael E. Hohman
Manager, Environmental Control

cc: Judith Katz, EPA III